



17TH FLOOR PLAN

Inspection summary:

1. Dead American cockroaches in many rooms.
2. Old moisture damage.